


LEFT FRONT WHEEL WELL




STEERING SECTION

SHINY AREA INDICATES
STRESS POINT DUE TO
RUBBING



MISSING
BOLTS
AFFECTED
BY STRESS





BROKEN
BOLT



BROKEN BOLT HEAD
FROM GEAR BOX

**PITTMAN ARM RUBBING SPRING
SHACKLE APPLYING PRESSURE TO
STEERING GEAR BOX BOLTS.**



**LEAF SPRING SHACKLE
CAN BE GROUND TO
PREVENT RUBBING.**

